

# USCG Integrated ATONIS

Integrated Aids to Navigation Information System

## Private Aid Assignment List

Filename : RPASN

Run by : REPORT\_USER2

Report Date : 03/14/2019 13:32

### Report Parameters

ATU : 13

OPFAC : 37400

Unit Responsibility Type : Secondary

# USCG Integrated ATONIS

Integrated Aids to Navigation Information System

## Private Aid Assignment List

RPASN

### CG SECTOR COLUMBIA RIV

<u>LLNR</u>	<u>Aid Name</u>	<u>Unit Role</u>	<u>Unit Name</u>
15847.1	Aberdeen Pontoon Basin Light A	Secondary	CG SECTOR COLUMBIA RIV
15847.2	Aberdeen Pontoon Basin Light B	Secondary	CG SECTOR COLUMBIA RIV
15847.3	Aberdeen Pontoon Basin Light C	Secondary	CG SECTOR COLUMBIA RIV
15847.4	Aberdeen Pontoon Basin Light D	Secondary	CG SECTOR COLUMBIA RIV
15847.5	Aberdeen Pontoon Basin Light E	Secondary	CG SECTOR COLUMBIA RIV
15820	Aberdeen Terminal 1 Pier Lights (2)	Secondary	CG SECTOR COLUMBIA RIV
15825	Aberdeen Terminal 2 Pier Lights (2)	Secondary	CG SECTOR COLUMBIA RIV
15793	Aberdeen Terminal 3 Pier Light (2)	Secondary	CG SECTOR COLUMBIA RIV
15845	Aberdeen Terminal 4 Pier Lights (2)	Secondary	CG SECTOR COLUMBIA RIV
12485	Arlington Grain Tower Light	Secondary	CG SECTOR COLUMBIA RIV
14905	Ash Grove Lime Dock Light N	Secondary	CG SECTOR COLUMBIA RIV
14906	Ash Grove Lime Dock Light S	Secondary	CG SECTOR COLUMBIA RIV
10084	Astoria West Basin Breakwater Light	Secondary	CG SECTOR COLUMBIA RIV
10075	Astoria West Basin Light 1	Secondary	CG SECTOR COLUMBIA RIV
10080	Astoria West Basin Light 2	Secondary	CG SECTOR COLUMBIA RIV
10083	Astoria West Basin Light 3	Secondary	CG SECTOR COLUMBIA RIV
15520	Bay Center Channel Daybeacon 13	Secondary	CG SECTOR COLUMBIA RIV
15528	Bay Center Channel Daybeacon 16	Secondary	CG SECTOR COLUMBIA RIV
10630	Beaver Pier East End Light	Secondary	CG SECTOR COLUMBIA RIV
10625	Beaver Pier West End Light	Secondary	CG SECTOR COLUMBIA RIV
12626.5	Boardman Water Intake Pipe Lighted Buoy A	Secondary	CG SECTOR COLUMBIA RIV
12627	Boardman Water Intake Pipe Lighted Buoy B	Secondary	CG SECTOR COLUMBIA RIV
12627.5	Boardman Water Intake Pipe Lighted Buoy C	Secondary	CG SECTOR COLUMBIA RIV
693	CMOP Research Lighted Buoy	Secondary	CG SECTOR COLUMBIA RIV
	CR M570 Fish Pen Lights (2)	Secondary	CG SECTOR COLUMBIA RIV
11454	Camas Slough Buoy 11	Secondary	CG SECTOR COLUMBIA RIV
11451	Camas Slough Buoy 6	Secondary	CG SECTOR COLUMBIA RIV
11452	Camas Slough Buoy 7	Secondary	CG SECTOR COLUMBIA RIV
11453	Camas Slough Buoy 9	Secondary	CG SECTOR COLUMBIA RIV
11802	Cascade Locks Warning Sign	Secondary	CG SECTOR COLUMBIA RIV
14935	Chevron Texaco Petroleum Dock Light A	Secondary	CG SECTOR COLUMBIA RIV
14940	Chevron Texaco Petroleum Dock Light B	Secondary	CG SECTOR COLUMBIA RIV
14016	Chief Timothy No Wake Buoy A	Secondary	CG SECTOR COLUMBIA RIV
14016.7	Chief Timothy No Wake Buoy H	Secondary	CG SECTOR COLUMBIA RIV
14016.8	Chief Timothy No Wake Buoy J	Secondary	CG SECTOR COLUMBIA RIV
14016.9	Chief Timothy No Wake Buoy K	Secondary	CG SECTOR COLUMBIA RIV
14016.3	Chief Timothy Regulatory Buoy D	Secondary	CG SECTOR COLUMBIA RIV
14016.4	Chief Timothy Regulatory Buoy E	Secondary	CG SECTOR COLUMBIA RIV
14016.5	Chief Timothy Regulatory Buoy F	Secondary	CG SECTOR COLUMBIA RIV
14016.6	Chief Timothy Regulatory Buoy G	Secondary	CG SECTOR COLUMBIA RIV
14016.1	Chief Timothy Regulatory Daybeacon B	Secondary	CG SECTOR COLUMBIA RIV
14016.2	Chief Timothy Regulatory Daybeacon C	Secondary	CG SECTOR COLUMBIA RIV
14017	Chief Timothy Water Intake Light	Secondary	CG SECTOR COLUMBIA RIV
11497	Chinook Landing Marine Park Light 1	Secondary	CG SECTOR COLUMBIA RIV
11498	Chinook Landing Marine Park Light 2	Secondary	CG SECTOR COLUMBIA RIV
10455	Chip Dock Light	Secondary	CG SECTOR COLUMBIA RIV
13053	Clover Island Lighthouse	Secondary	CG SECTOR COLUMBIA RIV
10633	Columbia River Geodetic Survey Light	Secondary	CG SECTOR COLUMBIA RIV
12035	Columbia View Orchards Water Intake Pipe Warning Light	Secondary	CG SECTOR COLUMBIA RIV
	Conkling Park Marina Light D	Secondary	CG SECTOR COLUMBIA RIV
	Conkling Park Marina Light E	Secondary	CG SECTOR COLUMBIA RIV
12111.3	Dallesport Boat Basin Dock Light A	Secondary	CG SECTOR COLUMBIA RIV
12111.1	Dallesport Boat Basin Light 1	Secondary	CG SECTOR COLUMBIA RIV
12111.2	Dallesport Boat Basin Light 2	Secondary	CG SECTOR COLUMBIA RIV
11015	Dyno Nobel Dock Lights (2)	Secondary	CG SECTOR COLUMBIA RIV

# USCG Integrated ATONIS

Integrated Aids to Navigation Information System

## Private Aid Assignment List

RPASN

### CG SECTOR COLUMBIA RIV

<u>LLNR</u>	<u>Aid Name</u>	<u>Unit Role</u>	<u>Unit Name</u>
10128	East Basin Boat Ramp Buoys 1	Secondary	CG SECTOR COLUMBIA RIV
10129	East Basin Boat Ramp Buoys 2	Secondary	CG SECTOR COLUMBIA RIV
10130	East Basin Boat Ramp Buoys 3	Secondary	CG SECTOR COLUMBIA RIV
10131	East Basin Boat Ramp Buoys 4	Secondary	CG SECTOR COLUMBIA RIV
10126	East Basin East Entrance Light 1	Secondary	CG SECTOR COLUMBIA RIV
10127	East Basin East Entrance Light 2	Secondary	CG SECTOR COLUMBIA RIV
10122	East Basin West Entrance Light 1	Secondary	CG SECTOR COLUMBIA RIV
10123	East Basin West Entrance Light 2	Secondary	CG SECTOR COLUMBIA RIV
10124	East Basin West Entrance Light 3	Secondary	CG SECTOR COLUMBIA RIV
10125	East Basin West Entrance Light 4	Secondary	CG SECTOR COLUMBIA RIV
10252	Elliot Point Research Lighted Buoy	Secondary	CG SECTOR COLUMBIA RIV
14925	Gasco Regulatory Buoys (3)	Secondary	CG SECTOR COLUMBIA RIV
11252	Grant Street Pier Light A	Secondary	CG SECTOR COLUMBIA RIV
11253	Grant Street Pier Light B	Secondary	CG SECTOR COLUMBIA RIV
14045	Greenbelt Sand Bar Warning Lighted Buoy A	Secondary	CG SECTOR COLUMBIA RIV
14045.1	Greenbelt Sand Bar Warning Lighted Buoy B	Secondary	CG SECTOR COLUMBIA RIV
14045.2	Greenbelt Sand Bar Warning Lighted Buoy C	Secondary	CG SECTOR COLUMBIA RIV
14045.3	Greenbelt Sand Bar Warning Lighted Buoy D	Secondary	CG SECTOR COLUMBIA RIV
	Hanford Reach Concrete Block Lighted Buoy 5	Secondary	CG SECTOR COLUMBIA RIV
	Hanford Reach Intake Pipe Lighted Buoy 1	Secondary	CG SECTOR COLUMBIA RIV
	Hanford Reach Intake Pipe Lighted Buoy 3	Secondary	CG SECTOR COLUMBIA RIV
11243	Hayden Island Anchorage Lighted Buoy A	Secondary	CG SECTOR COLUMBIA RIV
11244	Hayden Island Anchorage Lighted Buoy B	Secondary	CG SECTOR COLUMBIA RIV
13020	Hedges Terminal Wharf North Light	Secondary	CG SECTOR COLUMBIA RIV
13025	Hedges Terminal Wharf South Light	Secondary	CG SECTOR COLUMBIA RIV
14040	Hells Canyon Marina Sand Bar Warning Buoy A	Secondary	CG SECTOR COLUMBIA RIV
14040.1	Hells Canyon Marina Sand Bar Warning Buoy B	Secondary	CG SECTOR COLUMBIA RIV
14060	Hells Gate Water Intake Buoy	Secondary	CG SECTOR COLUMBIA RIV
11960	Hood River Breakwater Light	Secondary	CG SECTOR COLUMBIA RIV
11970	Hood River Marina Entrance East Light	Secondary	CG SECTOR COLUMBIA RIV
11965	Hood River Marina Entrance West Light	Secondary	CG SECTOR COLUMBIA RIV
14820	Houlihan Dock Light	Secondary	CG SECTOR COLUMBIA RIV
13222	Ice Harbor Lock Approach Coffey Cell Light 22	Secondary	CG SECTOR COLUMBIA RIV
13263	Ice Harbor Research Lighted Float	Secondary	CG SECTOR COLUMBIA RIV
12385	John Day Dam Lower Breakwater Light 2	Secondary	CG SECTOR COLUMBIA RIV
12390	John Day Dam Lower Guidewall Light A	Secondary	CG SECTOR COLUMBIA RIV
	John'S Landing Pier Light A	Secondary	CG SECTOR COLUMBIA RIV
	John'S Landing Pier Light B	Secondary	CG SECTOR COLUMBIA RIV
	John'S Landing Pier Light C	Secondary	CG SECTOR COLUMBIA RIV
	John'S Landing Pier Light D	Secondary	CG SECTOR COLUMBIA RIV
	John'S Landing Pier Light E	Secondary	CG SECTOR COLUMBIA RIV
	John'S Landing Pier Light F	Secondary	CG SECTOR COLUMBIA RIV
	John'S Landing Pier Light G	Secondary	CG SECTOR COLUMBIA RIV
10944	Kalama Shoal Isolated Danger Light Buoy K	Secondary	CG SECTOR COLUMBIA RIV
13027.5	Kalan Railroad Bridge RACON K	Secondary	CG SECTOR COLUMBIA RIV
13052	Kennewick Water Intake Lights (2)	Secondary	CG SECTOR COLUMBIA RIV
	Kenniwick Water Intake Lights (2)	Secondary	CG SECTOR COLUMBIA RIV
12873	Lake Wallula Pump Station Lighted Buoys (5)	Secondary	CG SECTOR COLUMBIA RIV
14965	Landing Boat Club Light 1	Secondary	CG SECTOR COLUMBIA RIV
14960	Landing Boat Club Light 2	Secondary	CG SECTOR COLUMBIA RIV
14975	Landing Boat Club Light 3	Secondary	CG SECTOR COLUMBIA RIV
14970	Landing Boat Club Light 4	Secondary	CG SECTOR COLUMBIA RIV
10811	Lewis And Clark Bridge Approach Buoy 1	Secondary	CG SECTOR COLUMBIA RIV
10812	Lewis And Clark Bridge Approach Buoy 2	Secondary	CG SECTOR COLUMBIA RIV
10813	Lewis And Clark Bridge Approach Buoy 3	Secondary	CG SECTOR COLUMBIA RIV

# USCG Integrated ATONIS

Integrated Aids to Navigation Information System

## Private Aid Assignment List

RPASN

### CG SECTOR COLUMBIA RIV

<u>LLNR</u>	<u>Aid Name</u>	<u>Unit Role</u>	<u>Unit Name</u>
10814	Lewis And Clark Bridge Approach Buoy 4	Secondary	CG SECTOR COLUMBIA RIV
	Lewis River Pekin Ferry No Wake Buoy A	Secondary	CG SECTOR COLUMBIA RIV
	Lewis River Pekin Ferry No Wake Buoy B	Secondary	CG SECTOR COLUMBIA RIV
	Lewis River Pekin Ferry No Wake Buoy C	Secondary	CG SECTOR COLUMBIA RIV
	Lewis River Pekin Ferry No Wake Buoy D	Secondary	CG SECTOR COLUMBIA RIV
13672.1	Little Goose Dam Fish Bypass Pipe Light A	Secondary	CG SECTOR COLUMBIA RIV
13672.2	Little Goose Dam Fish Bypass Pipe Light B	Secondary	CG SECTOR COLUMBIA RIV
13672.3	Little Goose Dam Fish Bypass Pipe Light C	Secondary	CG SECTOR COLUMBIA RIV
13672.4	Little Goose Dam Fish Bypass Pipe Light D	Secondary	CG SECTOR COLUMBIA RIV
13672.5	Little Goose Dam Fish Bypass Pipe Light E	Secondary	CG SECTOR COLUMBIA RIV
13672.6	Little Goose Dam Fish Bypass Pipe Light F	Secondary	CG SECTOR COLUMBIA RIV
13697	Little Goose Research Lighted Float	Secondary	CG SECTOR COLUMBIA RIV
10760	Longview Dock Light A	Secondary	CG SECTOR COLUMBIA RIV
10761	Longview Dock Light B	Secondary	CG SECTOR COLUMBIA RIV
10762	Longview Dock Light C	Secondary	CG SECTOR COLUMBIA RIV
10780	Longview Range Front Light	Secondary	CG SECTOR COLUMBIA RIV
10785	Longview Range Rear Light	Secondary	CG SECTOR COLUMBIA RIV
13937	Lower Granite Research Lighted Float	Secondary	CG SECTOR COLUMBIA RIV
13482.1	Lower Monumental Dam Fish Bypass Pipe Light A	Secondary	CG SECTOR COLUMBIA RIV
13482.2	Lower Monumental Dam Fish Bypass Pipe Light B	Secondary	CG SECTOR COLUMBIA RIV
13482.3	Lower Monumental Dam Fish Bypass Pipe Light C	Secondary	CG SECTOR COLUMBIA RIV
13482.4	Lower Monumental Dam Fish Bypass Pipe Light D	Secondary	CG SECTOR COLUMBIA RIV
13507	Lower Monumental Research Lighted Float	Secondary	CG SECTOR COLUMBIA RIV
11207	Lower Vancouver Anchorage Lighted Buoy V	Secondary	CG SECTOR COLUMBIA RIV
11304	Marine Park Outfall Daybeacon	Secondary	CG SECTOR COLUMBIA RIV
11303	Marine Park Outfall Light	Secondary	CG SECTOR COLUMBIA RIV
14930	McCormick and Baxter Buoy A	Secondary	CG SECTOR COLUMBIA RIV
14931	McCormick and Baxter Buoy B	Secondary	CG SECTOR COLUMBIA RIV
14932	McCormick and Baxter Buoy C	Secondary	CG SECTOR COLUMBIA RIV
14933	McCormick and Baxter Buoy D	Secondary	CG SECTOR COLUMBIA RIV
14934	McCormick and Baxter Buoy E	Secondary	CG SECTOR COLUMBIA RIV
12775.1	McNary Dam Outfall Pipe Light A	Secondary	CG SECTOR COLUMBIA RIV
12775.2	McNary Dam Outfall Pipe Light B	Secondary	CG SECTOR COLUMBIA RIV
12775.3	McNary Dam Outfall Pipe Light C	Secondary	CG SECTOR COLUMBIA RIV
12775.4	McNary Dam Outfall Pipe Light D	Secondary	CG SECTOR COLUMBIA RIV
12775.5	McNary Dam Outfall Pipe Light E	Secondary	CG SECTOR COLUMBIA RIV
12860	McNary Research Lighted Float	Secondary	CG SECTOR COLUMBIA RIV
15077.1	Meldrum Bar Daybeacon 1	Secondary	CG SECTOR COLUMBIA RIV
15077.2	Meldrum Bar Daybeacon 2	Secondary	CG SECTOR COLUMBIA RIV
15077.3	Meldrum Bar Daybeacon 3	Secondary	CG SECTOR COLUMBIA RIV
15077.4	Meldrum Bar Daybeacon 4	Secondary	CG SECTOR COLUMBIA RIV
	Nehalem River Buoys (46 Total)	Secondary	CG SECTOR COLUMBIA RIV
9880	Nehalem River Entrance Range Front Daybeacon	Secondary	CG SECTOR COLUMBIA RIV
9885	Nehalem River Entrance Range Rear Daybeacon	Secondary	CG SECTOR COLUMBIA RIV
15491.5	Nemah River Channel Daybeacon 10	Secondary	CG SECTOR COLUMBIA RIV
15491.6	Nemah River Channel Daybeacon 14	Secondary	CG SECTOR COLUMBIA RIV
15491.7	Nemah River Channel Daybeacon 16	Secondary	CG SECTOR COLUMBIA RIV
15491.8	Nemah River Channel Daybeacon 18	Secondary	CG SECTOR COLUMBIA RIV
15491	Nemah River Channel Daybeacon 2	Secondary	CG SECTOR COLUMBIA RIV
15491.9	Nemah River Channel Daybeacon 20	Secondary	CG SECTOR COLUMBIA RIV
15492	Nemah River Channel Daybeacon 22	Secondary	CG SECTOR COLUMBIA RIV
15491.1	Nemah River Channel Daybeacon 3	Secondary	CG SECTOR COLUMBIA RIV
15491.2	Nemah River Channel Daybeacon 4	Secondary	CG SECTOR COLUMBIA RIV
15491.3	Nemah River Channel Daybeacon 6	Secondary	CG SECTOR COLUMBIA RIV
15491.4	Nemah River Channel Daybeacon 8	Secondary	CG SECTOR COLUMBIA RIV

# USCG Integrated ATONIS

Integrated Aids to Navigation Information System

## Private Aid Assignment List

RPASN

### CG SECTOR COLUMBIA RIV

<u>LLNR</u>	<u>Aid Name</u>	<u>Unit Role</u>	<u>Unit Name</u>
15522	Niawiakum River Channel Daybeacon A	Secondary	CG SECTOR COLUMBIA RIV
15390.3	North River Channel Daybeacon 10	Secondary	CG SECTOR COLUMBIA RIV
15390.4	North River Channel Daybeacon 12	Secondary	CG SECTOR COLUMBIA RIV
15390.5	North River Channel Daybeacon 14	Secondary	CG SECTOR COLUMBIA RIV
15390.6	North River Channel Daybeacon 16	Secondary	CG SECTOR COLUMBIA RIV
15390.7	North River Channel Daybeacon 17	Secondary	CG SECTOR COLUMBIA RIV
15390.8	North River Channel Daybeacon 18	Secondary	CG SECTOR COLUMBIA RIV
15390.9	North River Channel Daybeacon 19	Secondary	CG SECTOR COLUMBIA RIV
15390	North River Channel Daybeacon 2	Secondary	CG SECTOR COLUMBIA RIV
15391	North River Channel Daybeacon 22	Secondary	CG SECTOR COLUMBIA RIV
15391.1	North River Channel Daybeacon 24	Secondary	CG SECTOR COLUMBIA RIV
15391.2	North River Channel Daybeacon 26	Secondary	CG SECTOR COLUMBIA RIV
15391.3	North River Channel Daybeacon 27	Secondary	CG SECTOR COLUMBIA RIV
15391.4	North River Channel Daybeacon 28	Secondary	CG SECTOR COLUMBIA RIV
15391.5	North River Channel Daybeacon 29	Secondary	CG SECTOR COLUMBIA RIV
15391.6	North River Channel Daybeacon 30	Secondary	CG SECTOR COLUMBIA RIV
15390.1	North River Channel Daybeacon 6	Secondary	CG SECTOR COLUMBIA RIV
15390.2	North River Channel Daybeacon 8	Secondary	CG SECTOR COLUMBIA RIV
728.5	OSU Westport Shelf Research Lighted Buoy	Secondary	CG SECTOR COLUMBIA RIV
14890	Oregon Steel Dock Lights (2)	Secondary	CG SECTOR COLUMBIA RIV
15030	Oswego North Dock Light	Secondary	CG SECTOR COLUMBIA RIV
15035	Oswego South Dock Light	Secondary	CG SECTOR COLUMBIA RIV
14065.32	Palouse River No Water Ski Restricted Area Buoy L	Secondary	CG SECTOR COLUMBIA RIV
14065.34	Palouse River No Water Ski Restricted Area Buoy M	Secondary	CG SECTOR COLUMBIA RIV
14065.1	Palouse River Submerged Pipeline Danger Buoy A	Secondary	CG SECTOR COLUMBIA RIV
14065.13	Palouse River Submerged Pipeline Danger Buoy B	Secondary	CG SECTOR COLUMBIA RIV
14065.15	Palouse River Submerged Pipeline Danger Buoy C	Secondary	CG SECTOR COLUMBIA RIV
14065.17	Palouse River Submerged Pipeline Danger Buoy D	Secondary	CG SECTOR COLUMBIA RIV
14065.2	Palouse River Submerged Pipeline Danger Buoy E	Secondary	CG SECTOR COLUMBIA RIV
14065.22	Palouse River Submerged Pipeline Danger Buoy F	Secondary	CG SECTOR COLUMBIA RIV
14065.24	Palouse River Submerged Pipeline Danger Buoy G	Secondary	CG SECTOR COLUMBIA RIV
14065.26	Palouse River Submerged Pipeline Danger Buoy H	Secondary	CG SECTOR COLUMBIA RIV
14065.28	Palouse River Submerged Pipeline Danger Buoy J	Secondary	CG SECTOR COLUMBIA RIV
14065.3	Palouse River Submerged Pipeline Danger Buoy K	Secondary	CG SECTOR COLUMBIA RIV
	Panhandle Yacht Club Light A	Secondary	CG SECTOR COLUMBIA RIV
	Panhandle Yacht Club Light B	Secondary	CG SECTOR COLUMBIA RIV
	Panhandle Yacht Club Light C	Secondary	CG SECTOR COLUMBIA RIV
13081	Pasco Water Intake Lighted Warning Buoy A	Secondary	CG SECTOR COLUMBIA RIV
13083	Pasco Water Intake Lighted Warning Buoy C	Secondary	CG SECTOR COLUMBIA RIV
13082	Pasco Water Intake Warning Daybeacon B	Secondary	CG SECTOR COLUMBIA RIV
13084	Pasco Water Intake Warning Daybeacon D	Secondary	CG SECTOR COLUMBIA RIV
15980	Point Chehalis Outfall Daybeacon	Secondary	CG SECTOR COLUMBIA RIV
12900	Port Kelley Range A Front Daybeacon	Secondary	CG SECTOR COLUMBIA RIV
12905	Port Kelley Range A Rear Daybeacon	Secondary	CG SECTOR COLUMBIA RIV
13101	Port Of Benton Barge Slip Buoy A	Secondary	CG SECTOR COLUMBIA RIV
13102	Port Of Benton Barge Slip Buoy B	Secondary	CG SECTOR COLUMBIA RIV
10891	Port Of Kalama Dock Light A	Secondary	CG SECTOR COLUMBIA RIV
10892	Port Of Kalama Dock Light B	Secondary	CG SECTOR COLUMBIA RIV
10893	Port Of Kalama Dock Light C	Secondary	CG SECTOR COLUMBIA RIV
10894	Port Of Kalama Dock Light D	Secondary	CG SECTOR COLUMBIA RIV
12481	Port of Arlington Marina Light 1	Secondary	CG SECTOR COLUMBIA RIV
12482	Port of Arlington Marina Light 2	Secondary	CG SECTOR COLUMBIA RIV
10894.5	Prescott Anchorage Lighted Buoy P	Secondary	CG SECTOR COLUMBIA RIV
12710	Pump Station Intake Light	Secondary	CG SECTOR COLUMBIA RIV
10830	Rainier Anchorage Lighted Buoy R	Secondary	CG SECTOR COLUMBIA RIV

# USCG Integrated ATONIS

Integrated Aids to Navigation Information System

## Private Aid Assignment List

RPASN

### CG SECTOR COLUMBIA RIV

<u>LLNR</u>	<u>Aid Name</u>	<u>Unit Role</u>	<u>Unit Name</u>
10828	Rainier Anchorage Lighted Buoy "RR"	Secondary	CG SECTOR COLUMBIA RIV
13100	Richland Water Intake Lights (2)	Secondary	CG SECTOR COLUMBIA RIV
14956	River Place Marina Breakwater Light A	Secondary	CG SECTOR COLUMBIA RIV
14957	River Place Marina Breakwater Light B	Secondary	CG SECTOR COLUMBIA RIV
14958	River Place Marina Breakwater Light C	Secondary	CG SECTOR COLUMBIA RIV
14959	River Place Marina Breakwater Light D	Secondary	CG SECTOR COLUMBIA RIV
14827.1	Saint Helens Regulatory Buoy A	Secondary	CG SECTOR COLUMBIA RIV
14827.2	Saint Helens Regulatory Lighted Buoy B	Secondary	CG SECTOR COLUMBIA RIV
14827.3	Saint Helens Regulatory Lighted Buoy C	Secondary	CG SECTOR COLUMBIA RIV
14832.1	Saint Helens Regulatory Lighted Buoy D	Secondary	CG SECTOR COLUMBIA RIV
14832.2	Saint Helens Regulatory Lighted Buoy E	Secondary	CG SECTOR COLUMBIA RIV
10928	Sandy Island Anchorage Lighted Buoy "S"	Secondary	CG SECTOR COLUMBIA RIV
14840.1	Scappoose Bay Daybeacon 1	Secondary	CG SECTOR COLUMBIA RIV
14840.3	Scappoose Bay Daybeacon 3	Secondary	CG SECTOR COLUMBIA RIV
14840.5	Scappoose Bay Daybeacon 5	Secondary	CG SECTOR COLUMBIA RIV
14840.7	Scappoose Bay Daybeacon 7	Secondary	CG SECTOR COLUMBIA RIV
14840.9	Scappoose Bay Daybeacon 9	Secondary	CG SECTOR COLUMBIA RIV
	Seal Slough Culvert Warning Sign A	Secondary	CG SECTOR COLUMBIA RIV
	Seal Slough Culvert Warning Sign B	Secondary	CG SECTOR COLUMBIA RIV
10832	Shaver Transportation Mooring Barge Lights (2)	Secondary	CG SECTOR COLUMBIA RIV
14955	Shaver Transportation Mooring Light	Secondary	CG SECTOR COLUMBIA RIV
14040.2	Slaughterhouse Warning Lighted Buoy C	Secondary	CG SECTOR COLUMBIA RIV
14051	Southway Boat Ramp Sand Bar Warning Buoy	Secondary	CG SECTOR COLUMBIA RIV
14055	Swallows Water Intake Lighted Buoy	Secondary	CG SECTOR COLUMBIA RIV
14950	Swan Island Pier A Light	Secondary	CG SECTOR COLUMBIA RIV
14945	Swan Island Pier C Light	Secondary	CG SECTOR COLUMBIA RIV
14943	Swan Island Pier D Light	Secondary	CG SECTOR COLUMBIA RIV
10943.1	TEMCO Marine Facility Light A	Secondary	CG SECTOR COLUMBIA RIV
10943.2	TEMCO Marine Facility Light B	Secondary	CG SECTOR COLUMBIA RIV
10943.3	TEMCO Marine Facility Light C	Secondary	CG SECTOR COLUMBIA RIV
10943.4	TEMCO Marine Facility Light D	Secondary	CG SECTOR COLUMBIA RIV
10943.5	TEMCO Marine Facility Light E	Secondary	CG SECTOR COLUMBIA RIV
10943.6	TEMCO Marine Facility Light F	Secondary	CG SECTOR COLUMBIA RIV
10943.7	TEMCO Marine Facility Light G	Secondary	CG SECTOR COLUMBIA RIV
10943.8	TEMCO Marine Facility Light H	Secondary	CG SECTOR COLUMBIA RIV
14923	Terminal 4 Daybeacon 13	Secondary	CG SECTOR COLUMBIA RIV
14875	Terminal 5 Bulk Outloader Dock Lights (2)	Secondary	CG SECTOR COLUMBIA RIV
10815.1	Terminal 9 Light A	Secondary	CG SECTOR COLUMBIA RIV
10815.2	Terminal 9 Light B	Secondary	CG SECTOR COLUMBIA RIV
10815.4	Terminal 9 Light D	Secondary	CG SECTOR COLUMBIA RIV
10815.5	Terminal 9 Light E	Secondary	CG SECTOR COLUMBIA RIV
10815.6	Terminal 9 Light F	Secondary	CG SECTOR COLUMBIA RIV
10815.7	Terminal 9 Light G	Secondary	CG SECTOR COLUMBIA RIV
10815.9	Terminal 9 Light J	Secondary	CG SECTOR COLUMBIA RIV
12114	The Dalles Commercial Dock Light B	Secondary	CG SECTOR COLUMBIA RIV
12116	The Dalles Commercial Dock Light C	Secondary	CG SECTOR COLUMBIA RIV
12112	The Dalles Commercial Dock Lighted Buoy A	Secondary	CG SECTOR COLUMBIA RIV
12119	The Dalles Outfall Daybeacon	Secondary	CG SECTOR COLUMBIA RIV
12306	Tidewater Mooring Barge Light A	Secondary	CG SECTOR COLUMBIA RIV
12311	Tidewater Mooring Barge Light B	Secondary	CG SECTOR COLUMBIA RIV
10942	Tidewater Mooring Barge Lights (2)	Secondary	CG SECTOR COLUMBIA RIV
10445	Unitizing Dock Light	Secondary	CG SECTOR COLUMBIA RIV
11245	Vancouver Upper Anchorage Lighted Buoy "VV"	Secondary	CG SECTOR COLUMBIA RIV
12907	Walla Walla Yacht Club Breakwater Light	Secondary	CG SECTOR COLUMBIA RIV
12942	Wallula Water Intake Light A	Secondary	CG SECTOR COLUMBIA RIV

# USCG Integrated ATONIS

Integrated Aids to Navigation Information System

## Private Aid Assignment List

RPASN

### CG SECTOR COLUMBIA RIV

<u>LLNR</u>	<u>Aid Name</u>	<u>Unit Role</u>	<u>Unit Name</u>
10440	Wauna Mill Water Intake Lighted Buoy A	Secondary	CG SECTOR COLUMBIA RIV
10428	Wauna Mill Water Outfall Lighted Buoy B	Secondary	CG SECTOR COLUMBIA RIV
15970	Weyerhauser Outfall Lights (2)	Secondary	CG SECTOR COLUMBIA RIV
11912	White Salmon Shoal Lighted Buoy 33	Secondary	CG SECTOR COLUMBIA RIV
10717	Willow Grove Boat Launch Light 1	Secondary	CG SECTOR COLUMBIA RIV
10718	Willow Grove Boat Launch Light 2	Secondary	CG SECTOR COLUMBIA RIV
10719	Willow Grove Deflection Boom Light & Warning Sign	Secondary	CG SECTOR COLUMBIA RIV
11857.4	Wind River Regulatory Buoy D	Secondary	CG SECTOR COLUMBIA RIV
11857.5	Wind River Regulatory Buoy E	Secondary	CG SECTOR COLUMBIA RIV
11857.6	Wind River Regulatory Buoy F	Secondary	CG SECTOR COLUMBIA RIV
11857.7	Wind River Regulatory Buoy G	Secondary	CG SECTOR COLUMBIA RIV
11857.8	Wind River Regulatory Buoy H	Secondary	CG SECTOR COLUMBIA RIV
11857.1	Wind River Regulatory Daybeacon A	Secondary	CG SECTOR COLUMBIA RIV
11857.2	Wind River Regulatory Daybeacon B	Secondary	CG SECTOR COLUMBIA RIV
11857.3	Wind River Regulatory Daybeacon C	Secondary	CG SECTOR COLUMBIA RIV
11857.9	Wind River Regulatory Daybeacon J	Secondary	CG SECTOR COLUMBIA RIV
11858	Wyeth Boat Ramp Breakwater Light 1	Secondary	CG SECTOR COLUMBIA RIV
11859	Wyeth Boat Ramp Breakwater Light 2	Secondary	CG SECTOR COLUMBIA RIV
14959.1	Zidell Regulatory Lighted Buoy A	Secondary	CG SECTOR COLUMBIA RIV
14959.2	Zidell Regulatory Lighted Buoy B	Secondary	CG SECTOR COLUMBIA RIV
14959.3	Zidell Regulatory Lighted Buoy C	Secondary	CG SECTOR COLUMBIA RIV