

SCR Housing Work Orders

Work Order #	Customer ID	Priority	Work Type	Work Order Comments	Target Completion Date
21-069	06486	2	Interior	damaged drywall was removed and will be replaced	Scheduled
21-166	15484	2	Appliance		Not Assigned
21-185	99061	2	Plumbing		Not Assigned
21-195	97165	2	Plumbing		Not Assigned
21-199	35401	2	Door		Not Assigned
19-363	95873	3	Garage	Warranty request. Awaiting contractor repair.	Not Assigned
20-132	18090	3	Hardware	Awaiting Parts	Scheduled
20-192	71855	3	Exterior	Deferred for COVID19	Not Assigned
20-193	71855	3	Exterior	Deferred for COVID19	Not Assigned
20-307	99974	3	Exterior	Submitted to HAT for repair.	Not Assigned
20-419	10686	3	Interior	started, needs follow up	Scheduled
20-436	97271	3	Interior		Not Assigned
20-444	51154	3	Interior		Not Assigned
21-007	61487	3	Garage		Not Assigned
21-008	61487	3	Kitchen		Not Assigned
21-009	61487	3	Exterior		Not Assigned
21-011	91664	3	Bathroom		Not Assigned
21-017	98568	3	Electrical		Not Assigned
21-020	61487	3	Interior	model/FGHT2132PP1 SER/4A40420666	Not Assigned
21-026	51526	3	Interior	Need to order proper size	Not Assigned
21-044	89899	3	Interior		Not Assigned
21-045	89899	3	Plumbing	Part on Order	Not Assigned
21-061	10777	3	Ventilation	EM2/ Parts are on order	Not Assigned
21-066	92480	3	Lighting		Not Assigned
21-072	97772	3	Interior		Not Assigned
21-073	21593	3	Interior		Not Assigned
21-075	21593	3	Exterior		Not Assigned
21-102	13606	3	Interior	needs follow up. Sched next week	Scheduled
21-104	88942	3	Interior	1/7/21	Not Assigned
21-125	15200	3	Exterior		Not Assigned
21-129	10990	3	Flooring		Not Assigned
21-143	51526	3	Door	we need a bifold to fit a 35" opening	Not Assigned
21-144	51526	3	Window	PEL-N-211 P5203367432. order sash balance	Scheduled
21-150	15200	3	Exterior		Not Assigned
21-155	15200	3	Window		Not Assigned
21-156	88349	3	Appliance	installed new gasket, no leaks on heavy wash	Not Assigned
21-172	000	3	Electrical		Not Assigned

SCR Housing Work Orders

Work Order #	Customer ID	Priority	Work Type	Work Order Comments	Target Completion Date
21-197	51154	3	Door		Not Assigned
21-198	51154	3	Door		Not Assigned
19-149	71855	4	Plumbing	Awaiting parts and weather.	Scheduled
19-154	000	4	Exterior	Request with CEU for multi-unit revitalization.	Scheduled
19-292	000	4	Exterior	Request with CEU for multi-unit revitalization.	Scheduled
19-343	12400	4	Plumbing	To be replaced on COM	Not Assigned
19-398	12452	4	Plumbing	To be replaced on COM	Not Assigned
19-679	59531	4	Exterior	Fencing will be removed from units	Not Assigned
20-109	21064	4	Electrical	To be completed time permitting	Not Assigned
20-270	01167	4	Exterior	Working with pella to get correct window	Not Assigned
20-276	12861	4	Appliance	Defered for SHI home H coded	Not Assigned
20-365	41502	4	Electrical		Not Assigned
20-370	35401	4	Bathroom		Not Assigned
20-374	35401	4	Bathroom		Not Assigned
20-439	92946	4	Interior		Not Assigned
21-096	91664	4	Electrical		Not Assigned